




Ball caster profile view
Scale 2:1

Ball caster section view
Scale 2:1

3 Ball caster isometric view Scale 2:1



4 Ball caster bottom view
Scale 2:1

1.

Intended for #2 and M2 screws.

To get the specified scale, select 100% in print settings.